

CORRES CONTROL
INCOMING LTR NO

2769 RF 93

DUE
DATE

ACTION

DIST LTR ENC

BENEDETTI, R L ☒
BENJAMIN, A
BERMAN, H S
CARNIVAL, G J
COPP, R D
CORDOVA, R C
DAVIS, J G
FERRERA, D W
HANNI, B J
HEALY, T J
HEDAH, T G
HILBIG, J G
KIRBY, W A
KUESTER, A W
LEE, E M
MANN, H P
MARX, G E
MCKENNA, F G
MORGAN, R V
PIZZUTO, V M
POTTER, G L
RILEY, J H
SANDLIN, N B
SATTERWHITE, D G
SCHUBERT, A L
SETLOCK, G H
SHEPLER, R L
SULLIVAN, M T
SWANSON, E R
WILKINSON, R B
WILSON, J M
ZANE, J O

Primrose ☒
A

Busby ☒
W

CORRES CONTROL ☒ ☒

Reviewed for Addressee
Corres Control RFP

6-25-93
DATE BY

Ref Ltr #

Department of Energy

ROCKY FLATS OFFICE
P O BOX 928
GOLDEN COLORADO 80402-0928

JUN 23 1993

93-DOE-07308

JUN 25 10 00 AM '93
ROCKY FLATS PLU T
CORRESPONDENCE

Mr Martin Hestmark
U S Environmental Protection Agency, Region VIII
ATTN Rocky Flats Project Manager, 8HWM-RI
999 18th Street, Suite 500, 8WM-C
Denver, Colorado 80202-2405

Mr Gary Baughman
Hazardous Waste Facilities Unit Leader
Colorado Department of Health
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530


Gentlemen

We are transmitting copies of the document entitled "Draft Soil Vapor Extraction Pilot Test Plan, Site No 2, Enhanced Vapor Extraction of Organic Compounds with Electrical Heating, East Trenches Area, Operable Unit 2," dated June 1993. This draft document represents the second test plan under the OU2 Subsurface Interim Measure/Interim Remedial Action (IM/IRA). As discussed in our June 4, 1993, letter (93-DOE-05204) to you, this document is due to you June 24, 1993.

The proposed location of Test 2 has been moved from the Mound area to IHSS 111 1 because of the quantity of Volatile Organic Compounds (VOC) available for removal. Preliminary review of site data indicates the level of VOCs at the Mound area to be at or near analytical detection limits, and therefore too low for meaningful testing. However, if the results of the soil vapor survey, currently being performed, show adequate VOC concentrations, we will reevaluate our proposal not to conduct Test 2 at the Mound area.

If you have any questions, please contact Scott Grace of my staff at (303) 966-7199.

Sincerely,


James K. Hartman
Assistant Manager for Transition
and Environmental Restoration

Enclosure

cc w/ Enclosure
A Rampertaap, EM-453

ADMIN RECORD

JUN 23 1993

M Hestmark & G Baughman
93-DOE-07308

2

cc w/o Enclosure
~~A. Primrose, EG&G~~
G Kleeman, EPA
J Schieffelin, CDH